



Action Required:

Asset ID# FE0012345

Action: This fire extinguisher is required to be tipped upside down to prevent compaction of powder.

Action: Lubricate components for rust prevention.

